



ENVIRONMENT
AGENCY

AMCO GIFFEN



Location: Long Street, Croscombe

Date: 08/12 /2020

Asset ID: 152156

Contractor Details

The contractor working on behalf of The Environment Agency for this project is:

Glanville Environmental

Unit 2

Central Court

Central Avenue

Lee Mill Industrial Estate

Ivybridge

PL21 9PE

General Details

Carry out CCTV survey Investigation to ascertain the Structural condition of the Culvert within the area of Long Street, Croscombe.

The survey was carried out in December in dry weather conditions.

The method of the survey was CCTV

The Survey team consisted of: - CCTV crew & Confined space entry team

➤ CCTV / Confined space

Survey works were completed without incident and no gas or dangerous substances were detected within the culvert or surrounding location.

Notes – No U/S survey unable to gain access & WL too high

Access issues. Unable to gain access to Outlet



ENVIRONMENT
AGENCY

AMCO GIFFEN



Location: Long Street, Crocombe

Date: 08/12 /2020

Asset ID: 152156

Inspection Summary

Defects:

- MH2 – Outlet - Deformed to 10%. Missing mortar. Displace masonry. Debris to 10%. Obstruction to 25% (Tree branch)

Remedial Action required:

- MH2 – Outlet – Carry out cleaning of asset throughout section length & monitor other defects identified within the CCTV report

Estimated cost of remedial action: Based on all of the above: - Less than £5000

Mean grading score of Culvert based on WRC condition grading: Service 4, Structural 3

Mean Grading score based on Condition grading: 3

Life Expectancy: 10 years+ once remedial works carried out.



ENVIRONMENT
AGENCY

AMCO GIFFEN



Location: Long Street, Crocombe

Date: 08/12 /2020

Asset ID: 152156

Site Photos

MH2 Cover



Outlet Headwall



MH2 Chamber



Outlet Location



MH2 Location

