



Site: Long Street, Croscombe

Surveyed Date: 17/03/2017

Asset ID: 152157

Contractor Details

The contractor working on behalf of The Environment Agency for this project is:

Glanville Environmental

Unit 2
Central Court
Central Avenue
Lee Mill Industrial Estate
Ivybridge
PL21 9PE

General Details

Carry out CCTV survey Investigation to ascertain the Structural condition of the Culvert within the area of Long Street, Croscombe.

The survey was carried out in March 2017 in dry weather conditions.

The method of the survey was CCTV/Confined Space Survey

The Survey team consisted of:-

- CCTV Unit & Confined Space Survey Team
- GPS Survey Team

Survey works were completed without incident and no gas or dangerous substances were detected within the culvert or surrounding location.

Notes –

No access issues.



Site: Long Street, Croscombe

Surveyed Date: 17/03/2017

Asset ID: 152157

Inspection Summary

Defects:

- SMH1 ---SMH2 – Settled Deposits & Connection Intruding.

Remedial Action required: Concentrated HPJ to remove Settled Deposits. Remove Intruding Connection and make good Culvert wall.

Estimated cost of remedial action: Based on all of the above: - Less than £5000

Mean grading score of Culvert based on WRC condition grading: Service 3, Structural 1

Mean Grading score based on Condition grading: 2

Life Expectancy: 10 years+ once remedial works carried out.



Site: Long Street, Croscombe

Surveyed Date: 17/03/2017

Asset ID: 152157

Site Photos - SMH1 Chamber



SMH1 Upstream



SMH1 Downstream



SMH2 Chamber



SMH1 Location



SMH2 Downstream





Site: Long Street, Croscombe

Surveyed Date: 17/03/2017

Asset ID: 152157

SMH2 Location



SMH2 Upstream

